



---

## Fleet Wash<sup>®</sup> NPA

### Fleet Wash Brightener

---

**FLEET WASH<sup>®</sup> NPA** is a clear, phosphorous free, acidic liquid specially formulated to rapidly remove soils and oxide accumulations from aluminum, stainless steel, brass, painted surfaces, steel and copper.

**BENEFITS:** When applied and rinsed as directed, **FLEET WASH<sup>®</sup> NPA** is safe on the following surfaces: bronze, aluminum, stainless steel, copper, iron, steel, brass, rubber, and lead. **FLEET WASH<sup>®</sup> NPA** contains no phosphates, making it more environmentally friendly than most other truck washes. **FLEET WASH<sup>®</sup> NPA** quickly brightens aluminum and other oxidized surfaces. Use in conjunction with **FLEET WASH<sup>®</sup> S** to remove grease, oil, road film and other soils.

**DIRECTIONS:** Dilute **FLEET WASH<sup>®</sup> NPA** with water before use. The proper dilution depends on the condition of the aluminum, or other metals, the dwell time available, the ambient temperature, and the equipment available. Typically dilutions are 1:10-1:50. Apply **FLEET WASH<sup>®</sup> NPA** through acid proof, low pressure or high pressure equipment. **FLEET WASH<sup>®</sup> NPA** can be applied in a Drive Through Fleet wash system. Do not allow solution to dry on the surface, and furnish a complete rinse by flooding.

**CAUTION: FLEET WASH<sup>®</sup> NPA** contains hydrofluoric and sulfuric acids. Avoid contact. Corrosive to skin and eyes. If splashed in eyes, flush with large amounts of water and consult physician. If splashed on skin, flush with water and wash with soap and water. Harmful or fatal if swallowed. If swallowed, give water or milk. Follow with olive oil. Consult a physician. Vapors harmful. Avoid breathing excessive vapors.

**NFPA Code:** Health - 3, Fire - 0, Reactivity - 0, Special - Acid

- **Non-phosphorus**
- **Safe on Metals & Rubber**
- **Removes Oil, Tar, & Soils Effortlessly**
- **Environmentally Friendly**